



AJ IFW 10/772340 CFC

PATENT
Customer No. 22,852
Attorney Docket No. 2508.0095-01

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.: 6,966,979)
Inventor: Renato Pedrazzi) Certificate
Issue Date.: November 22, 2005) MAR 21 2006
For: DEVICE AND METHOD FOR)
CONTROLLING INFUSION OF A)
LIQUID IN AN EXTRACORPOREAL)
BLOOD CIRCUIT)
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

SECOND REQUEST FOR CERTIFICATE OF CORRECTION

Pursuant to 35 U.S.C. §§ 254 and 255, and 37 C.F.R. §§ 1.322 and 1.323, this is a second request for a Certificate of Correction in the above-identified patent. The mistake identified in the appended Form occurred through the fault of the Patent Office, as clearly disclosed by the records of the application which matured into this patent.

Two (2) copies of PTO Form 1050 are appended. The complete Second Certificate of Correction involves one (1) page. Issuance of the Second Certificate of Correction containing the correction is earnestly requested.

MAR 27 2006

Please charge any required fees not included herewith to our deposit account
06-0916.

Respectfully submitted,

FINNEGAN, HENDERSON, FARABOW,
GARRETT & DUNNER, L.L.P.

Dated: March 17, 2006

By: 

Aaron L. Parker
Reg. No. 50,785

UNITED STATES PATENT AND TRADEMARK OFFICE
SECOND CERTIFICATE OF CORRECTION

PATENT NO. 6,966,979 Page 1 of 1

APPLICATION NO.: 10/772,340

ISSUE DATE: November 22, 2005

INVENTOR: Renato Pedrazzi

It is hereby certified that an error appears in the Original Certificate of Correction of the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Under Column 8, line 19, "FF=UFR/[Q_q=UFR/[Q_b·(1-Hct)]]" should read
--FF=UFR/Q_p=UFR/[Q_b·(1-Hct)]--.

This error is the fault of the Patent & Trademark Office.

MAILING ADDRESS OF SENDER

Finnegan, Henderson, Farabow,
Garrett & Dunner, L.L.P.
901 New York Avenue, N.W.
Washington, D.C. 20001-4413

MAR 2 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
SECOND CERTIFICATE OF CORRECTION

PATENT NO. 6,966,979

Page 1 of 1

APPLICATION NO.: 10/772,340

ISSUE DATE: November 22, 2005

INVENTOR: Renato Pedrazzi

It is hereby certified that an error appears in the Original Certificate of Correction of the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Under Column 8, line 19, "FF=UFR/[Q_q=UFR/[Q_b·(1-Hct)]]" should read

--FF=UFR/Q_p=UFR/[Q_b·(1-Hct)]--.

This error is the fault of the Patent & Trademark Office.

MAILING ADDRESS OF SENDER

Finnegan, Henderson, Farabow,
Garrett & Dunner, L.L.P.
901 New York Avenue, N.W.
Washington, D.C. 20001-4413

MAR 27 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,966,979 B2
DATED : November 22, 2005
INVENTOR(S) : Renato Pedrazzi

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page.

Item [74], *Attorney, Agent, or Firm*, "Finnegan, Henderson, Farabow, Dunner & Dunner, L.L.P." should read -- Finnegan, Henderson, Farabow, Garrett & Dunner, L.L.P. --.

Column 7.

Line 26, "trans-membrane" should read -- transmembrane --.
Line 63, "pine" should read -- pipe --.

Column 8.

Line 19, "FF=UFR/Q_q=UFR/[Q_b·(1-Hct)]" should read
-- FF=UFR/[Q_p=UFR/[Q_b·(1-Hct)]] --.
Line 20, "Q_q" should read -- Q_p --.

Column 9.

Line 4, "FF=UFR/Q_q=UFR/[Q_b·(1-Hct)]" should read -- FF=UFR/Q_p=UFR/[Q_b·(1-Hct)] --.
Line 5, "Q_q" should read -- Q_p --.
Line 10, "trans-membrane" should read -- transmembrane --.

Column 10.

Line 26, "FF=UFR/Q_q=UFR/[Q_p·(1-Hct)]" should read -- FF=UFR/Q_p=UFR/[Q_b·(1-Hct)] --.
Line 27, "Q_q" should read -- Q_p --.
Line 32, "trans-membrane" should read -- transmembrane --.

Signed and Sealed this

Twenty-eighth Day of February, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office